

Follow the steps below to update firmware of the Lightning adapter for Gateway:

1. Extract the **LIAA_UPD.ROM** file from the update package
2. Copy the **LIAA_UPD.ROM** to the root folder of a USB drive (FAT32 file system with only one partition)
3. Turn the ignition ON in the car and switch the head unit ON
4. Wait until the head unit recognizes the Gateway and select it as a source
5. Connect the Lightning adapter (LIA) to the Dock Cable port of the Gateway
6. Connect the flash drive with the update file to the USB port of the Lightning adapter
7. Wait 20 seconds
8. Disconnect the USB flash drive and check the **LIAA_NFO.nfo** using 'Notepad' (or similar). In the second line of the file you should see the firmware version of the Lightning adapter. It should be the new version.

If you need further assistance in using your Lightning adapter for Gateway, please contact your local supplier or visit www.dension.com and click on 'Support'.