

Follow the steps below to update firmware:

Extract the **G31B_UPD.rom** file from the update package, copy the file to the root of a USB flash drive and then connect the USB drive to the Gateway Pro BT's while it is powered up (**ignition ON**). If possible please also **copy 2-3 MP3 files** to the **USB device**, again to the root. If there is an iPod connected to Gateway, please disconnect it before you connect the USB drive.

The update procedure will start automatically within a few seconds and takes approximately **2 minutes**. During the update procedure the Gateway Pro BT will restart a couple of times. **Do not disconnect the USB drive or turn the ignition OFF within this time (!)**.

When finished, you may need to reselect Gateway again from the Head Unit (car stereo).

After a successful update the **G31B_UPD.rom** is deleted from the USB flash drive and the new software version number will be visible in the Gateway **Settings\About** menu.

Test the Gateway Pro BT functionalities. For more information read [Knowledge Base](#).

We do appreciate also if you can give us a feedback about the result, therefore please go to www.dension.com click on 'Support' and create a support ticket.

Please note: Although we do support playing music content from a USB hard disk drive, for the firmware update please use a USB flash stick/pen drive.

Important note for Peugeot or Citroen users: **Start the engine** before perform a firmware update in order to avoid '**Economy mode**' activation