






# Installation in Toyota/Lexus cars after 2008 model year with HDD



Select Toyota (Kenwood) protocol in CS9100 / CS9200 settings (SPT-100)

	CS 9100	CS8000	GARMIN
SW1	OFF	OFF	OFF
SW2	OFF	OFF	OFF
SW3	ON	ON	ON
SW4			
SW5	ON	OFF	OFF
SW6	OFF	ON	OFF
SW7	OFF	OFF	ON
SW8	OFF	OFF	OFF



For cars with external Park Assist module SW4 - OFF

For cars with camera connected to monitor SW4 - ON